

Asia Pacific

PSC Hong Kong
 Hong Kong
 Telephone: [852]-2-584-6210
 Telefax: [852]-2-521-0291

Australia

PSC Asia Pacific Pty Ltd.
 North Ryde, Australia
 Telephone: [61]0(2)9878 8999
 Telefax: [61]0(2)9878 8688

France

PSC Sarl
 LES ULIS Cedex, France
 Telephone: [33].1.64.86.71.00
 Telefax : [33].1.64.46.72.44

Germany

PSC GmbH
 Darmstadt, Germany
 Telephone: + 49 (0) 61 51/93 58 - 0
 Telefax: + 49 (0) 61 51/93 58 58

Italy

PSC S.r.l.
 Vimercate (MI), Italy
 Telephone: 039/62903.1
 Telefax: 039/6859496

Japan

PSC Japan K.K.
 Shinagawa-ku, Tokyo, Japan
 Telephone: 81 (0)3 3491 6761
 Telefax: 81 (0)3 3491 6656

Latin America

PSC S.A., INC.
 Miami, Florida, USA
 Telephone: (305) 539-0111
 Telefax: (305) 539-0206

United Kingdom

PSC Bar Code Ltd.
 Watford, England
 Telephone: 44 (0) 1923 809500
 Telefax: 44 (0) 1923 809 505

**Corporate Headquarters**

675 Basket Road
 Webster, NY 14580-9787
 Telephone: (716) 265-1600
 Toll Free: (800) 828-6489
 Telefax: (716) 265-6400

www.pscnet.com

PSC Scanning, Inc.

959 Terry Street
 Eugene, OR 97402-9150
 Telephone: (541) 683-5700
 Toll Free: (800) 547-2507
 Telefax: (541) 686-1702



Printed on recycled paper



R44-1546 (Rev C)

Printed in USA 5/98

© 1998 PSC INC.

PSC QUICKSCAN™

6000/6000 plus

UNDECODED INTERFACE

Since the Undecoded Interface (I/F) has no programmable features, enabling the interface is simply a matter of connecting the scanner to your system using the proper PSC approved QuickScan 6000/QuickScan 6000 Plus I/F cable.

WARNING

Connection using an unapproved cable can result in damage to the scanner. Approved PSC cables can be recognized as those having a cable I.D. code printed on a white label, approximately 1" in length, attached to them.

To disconnect the I/F cable at the scanner, insert a bent paper clip or 0.050" hex driver into the opening marked CABLE RELEASE as shown in the figure below, and push inward. Once the connector latch is released, continue to hold in on the latch while carefully pulling the cable free.

